



CONCESIONARIO OFICIAL SANTANA

SUZUKI - 12810-79J81-000 - TENSOR CORREA DISTRIBUCION

Tensor correa distribucion

TENSIONER

TENDEUR

TENDITORE

SPANNER

Marca Referencia

Suzuki 1281079J81

Vehiculo Código de modelo Modificación motor

SX4 RW420 RW420D-3 (MAGYAR) RW420D TYPE 3


SX4 RW420 RW420D-4 (MAGYAR) RW420D TYPE 4

SX4 AKK416 AKK416 (P02,P22,P24,P90) M16A

SX4 AKK416 AKK416D (P02,P22,P24,P90)

SX4 AKK416 AKK416 (P71) M16A

FIG.49



RW415 E22 049
TIMING BELT (3)