



CONCESIONARIO OFICIAL SANTANA

SANTANA - 11349-85C00 - JUNTA ALOJAMIENTO RETEN E22

Junta alojamiento reten

GASKET, OIL SEAL HOUSING

JOINT, BOÎTIER DE JOINT D'HUILE

Vehiculo Código de modelo Modificación Tipo

Samurai/SJ SJ419 SJ419 (MY:99, Santana)

Samurai/SJ SJ419 SJ419D (MY:99, Santana)

Samurai/SJ SJ419 SJ419TD (MY:99, Santana)

Vitara/Sidekick SE419 SE419D (MY:96, 5DR Santana) 5DR

Vitara/Sidekick SE419 SE419TD (MY:97-98, Santana)

Jimny SN413 SN413V-2 (SANTANA) TYPE 2 PETROL

Vitara/Sidekick SE416 SE416 (MY:97-98, Santana)

Samurai/SJ SJ413 SJ413 E-III (Santana)

Vitara/Sidekick SE416 SE416 E-III (Santana)

Vitara/Sidekick SE416 SE416 (MY:96, 3DR Santana) 3DR

Vitara/Sidekick SE419 SE419D (MY:96, 3DR Santana) 3DR

Vitara/Sidekick SE416 SE416 (MY:~95, Santana)

Vitara/Sidekick SE416 SE416 (MY:96, 5DR Santana) 5DR

Jimny SN413 SN413Q (SANTANA) TYPE 1

Jimny SN413 SN413Q-2 (SANTANA) TYPE 2

