



CONCESIONARIO OFICIAL SANTANA

SANTANA - 78532-62A00 - PERFIL LAT.DEL.L/I FAST TOP

Perfil lateral delantero izquierdo

GARNISH, PILLAR LEFT HAND

GARNITURE, PILIER MAIN GAUCHE

GUARNIZIONE, PILASTRO LATO SINISTRO

DICHTUNG, LINKE SÄULE

Vehículo Código de modelo Modificación Carrocería

Vitara/Sidekick SV418 SV418 (MY 1997) 97 MODEL SV418

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1995) 95 MODEL

Vitara/Sidekick SV418 SV418 (MY 1996) 96 MODEL SV418

Vitara/Sidekick SE419 SE419TD (MY:97-98,Santana)

Vitara/Sidekick SE416 SE416 (E03,E28,E33,E60:MY 1998) 98 MODEL SE416

Vitara/Sidekick SE416 SE416 (MY:97-98, Santana)

Vitara/Sidekick SE416 SE416 (E03,E28,E33,E60:MY 1997) 97 MODEL SE416

Vitara/Sidekick SE416 SE416 (E03,E28,E33,E60:MY 1996) 96 MODEL SE416

Vitara/Sidekick SE416 SE416 E-III (Santana)

Vitara/Sidekick SV418 SV418 (MY 1998) 98 MODEL SV418

Vitara/Sidekick SE420 SE420 HDI 3DR (Santana) 3DR

Vitara/Sidekick SE416 SE416 (E28:MY 1995) 95 MODEL

Vitara/Sidekick SE420 SE420 HDI 5DR (Santana) 5DR



FIG.187



