



SANTANA - 84651-60A00 - JUNTA GOMA L/I

Junta goma lado izquierda

WEATHERSTRIP, FR DR OPNG LH

JOINT D'ÉTANCHÉITÉ, FR DR OPNG LH

Vehículo Códigos de modelo Código de modelo

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1991) 91 MODEL

Vitara/Sidekick SE416 SE416-2 (Santana) TYPE 2

Vitara/Sidekick SE413 SE413

Vitara/Sidekick SE416 SE416-3 (Santana) TYPE 3

Vitara/Sidekick SE416 SE416 (Santana) TYPE 1

Vitara/Sidekick SE416 SE416 (E28:MY 1989) 89 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1991) 91 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1990) 90 MODEL

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1989) 89 MODEL

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1990) 90 MODEL

