



CONCESIONARIO OFICIAL SANTANA

LAND ROVER - 505805 - TORNILLO DE CONEXION

Tornillo superior del filtro de combustible

BANJO BOLT TOP OF FUEL FILTER DIESEL 1968 - 1990

BOULON BANJO SUR LE DESSUS DU FILTRE À CARBURANT DIESEL 1968 - 1990

BULLONE BANJO SOPRA FILTRO CARBURANTE DIESEL 1968 - 1990

HOHLSCHRAUBE OBEN AUF DEM DIESEL-KRAFTSTOFFFILTER 1968 - 1990

Compatibilidad

Series 3

Series 2

Defender



RECAMBIOS ORIGINALES

SANTANA

505805

127

1



PIECES D'ORIGINE

SAN

NE PARTS

TANA