



CONCESIONARIO OFICIAL SANTANA

SANTANA - 13125-60A00 - JUNTA CARBURADOR

Junta Carburador

GASKET, CARBURETOR

JOINT, CARBURATEUR

GUARNIZIONE, CARBURATORE

DICHTUNG, VERGASER

Vehiculo Código de modelo ??dificación Tipo

Vitara/Sidekick SE416 SE416-5 TYPE 5

Vitara/Sidekick SE416 SE416 (3DR) TYPE 1

Vitara/Sidekick SE416 SE416-4 TYPE 4

Vitara/Sidekick SE416 SE416 (E24) TYPE 1

Vitara/Sidekick SE416 SE416-2 (E24) TYPE 2

Vitara/Sidekick SE416 SE416-3 (3DR) TYPE 3

Vitara/Sidekick SE416 SE416-2 (3DR) TYPE 2

Vitara/Sidekick SE416 SE416-3 (E24) TYPE 3



スズキ純正部品

SUZUKI GENUINE PARTS

PIÈCES D'ORIGINE DE SUZUKI

PART NO.

モーター株式会社

13125-60A00




QUANTITY
(QUANTITE)

1

150909

MADE IN JAPAN / FABRIQUE AU JAPON

SUZUKI MOTOR CORPORATION



SE416-4 E01_022
INTAKE MANIFOLD(2V:CARB:AT)