



CONCESIONARIO OFICIAL SANTANA

SANTANA - 13601-841T0 - JUEGO DE TORNILLO DE AJUSTES

Juego tornillos de ajuste

Vehiculo Código de modelo Modificación Tipo

Vitara/Sidekick SE416 SE416-5 TYPE 5

Vitara/Sidekick SE416 SE416 (3DR) TYPE 1

Vitara/Sidekick SE416 SE416-4 TYPE 4

Vitara/Sidekick SE419 SE419TD (MY:97-98,Santana)

Vitara/Sidekick SE416 SE416 (E24) TYPE 1


Vitara/Sidekick SE416 SE416-2 (E24) TYPE 2

Vitara/Sidekick SE416 SE416 (MY:97-98, Santana)

Vitara/Sidekick SE416 SE416-3 (3DR) TYPE 3

Vitara/Sidekick SE416 SE416-2 (3DR) TYPE 2

Vitara/Sidekick SE416 SE416-3 (E24) TYPE 3



SE416 3DR E01 033
CARBURETOR (1)