



CONCESIONARIO OFICIAL SANTANA

SANTANA - 13948-84A00 - TORNILLO CONECTOR LADO B

Tornillo conector lado B

BOLT, UNION ENG SIDE

BOULON, UNION COTE MOT

Vehículo Código de modelo ??dificación fuel ?odelo

Jimny SN415 SN415QD-3 (SANTANA) DIESEL SN415QD

Jimny SN415 SN415VD-6 DIESEL SN415VD TYPE 6

Jimny SN415 SN415QD (SANTANA) DIESEL

Jimny SN415 SN415VD-4 DIESEL SN415VD TYPE 4

Jimny SN415 SN415VD-4 (SANTANA) DIESEL SN415VD

Jimny SN415 SN415VD-5 DIESEL SN415VD TYPE 5

Jimny SN415 SN415VD-7 DIESEL SN415VD TYPE 7

Jimny SN413 SN413Q (SANTANA) TYPE 1

Jimny SN413 SN413Q-2 (SANTANA) TYPE 2

Jimny SN415 SN415QD-4 (SANTANA) DIESEL SN415QD

