



# CONCESIONARIO OFICIAL SANTANA

## SANTANA - 16119-82012 - JUNTA BOMBA DE ACEITE

Junta bomba de aceite

OIL PUMP SEAL

JOINT DE POMPE À HUILE

GUARNIZIONE POMPA OLIO

ÖLPUMPENDICHTUNG

Marca Referencia

Suzuki 1611982000

Vehículo ??dificación

Samurai/SJ SJ413/SJ413Q/SJ413V (E24)

Samurai/SJ SJ413W-4 (E24)

Forsa/Sprint/Swift (SA) SA310-3 (E28:MY 1988) 88 MODEL

Samurai/SJ SJ413Q-4/SJ413V-4/SJ413W-4 (E01)

Samurai/SJ SJ413W-2 (E24)

Forsa/Sprint/Swift (SA) SA310 (E28)

Samurai/SJ SJ413 (E03,E33:MY 1988 1/2)

Samurai/SJ SJ413 (Santana) (E22)

Samurai/SJ SJ413K (E28)

Samurai/SJ SJ413P-2 (E01)

Samurai/SJ SJ413W-3 (E01)

Forsa/Sprint/Swift (SA) SA310 (E01)

Samurai/SJ SJ413K-2/SJ413P-2 (E24)

Samurai/SJ SJ413V (E01)

Forsa/Sprint/Swift (SA) SA413

Samurai/SJ SJ413 (E03,E33:MY 1988) 88 MODEL

Samurai/SJ SJ413K/SJ413P (E24)

Samurai/SJ SJ413V-3 (E01)

Samurai/SJ SJ413-3/SJ413Q-3/SJ413V-3 (E24)

Samurai/SJ SJ413K-3 (E01)

Samurai/SJ SJ413W-2 (E01)

Samurai/SJ SJ413W-3 (E24)

Vitara/Sidekick SE413

Samurai/SJ SJ413 (E03,E33:MY 1989) 89 MODEL

Samurai/SJ SJ413K-2 (E01)

Samurai/SJ SJ413P-3 (E01)

Samurai/SJ SJ413 (E03,E33:MY 1986) 86 MODEL

Samurai/SJ SJ413/SJ413Q (E28)  
Samurai/SJ SJ413K-3/SJ413P-3 (E24)  
Samurai/SJ SJ413/SJ413Q (E01)  
Samurai/SJ SJ413-2/SJ413Q-2 (E01)  
Samurai/SJ SJ413V (E28)  
Samurai/SJ SJ413-2/SJ413Q-2/SJ413V-2 (E24)  
Samurai/SJ SJ413K (E01)  
Samurai/SJ SJ413-3/SJ413Q-3 (E01)  
Samurai/SJ SJ413Q-4/SJ413V-4 (E24)  
Samurai/SJ SJ413V-2 (E01)  
Forsa/Sprint/Swift (SA) SA310-3 (E28:MY 1987) 87 MODEL  
Samurai/SJ SJ413P (E01)  
Forsa/Sprint/Swift (SA) SA413-3  
Samurai/SJ SJ413Q-5/SJ413V-5 (E01)  
Samurai/SJ SJ413W (E28)  
Samurai/SJ SJ413 (E03,E33:MY 1987) 87 MODEL  
Samurai/SJ SJ413Q-5/SJ413V-5 (E24)  
Forsa/Sprint/Swift (SA) SA310-3 (E01)  
Samurai/SJ SJ413W (E01)  
Samurai/SJ SJ413W (E24)

**GRUPO JPC**  
MANUTENCIÓN · REPARACIÓN · RECAMBIO  
RECAMBIO ORIGINAL  
GENUINE PARTS

**P/Nº: 16119-82012**

**Cant: 1**

**JUNTA BOMBA DE ACEITE SAMUR**



