



CONCESIONARIO OFICIAL SANTANA

SANTANA - 17887-86CA0 - TUBO DE LONGITUD 186

Tubo lubricacion

UNION 186

UNION 186

Vehículo ??dificación

Vitara/Sidekick SE419D (Santana)

Samurai/SJ SJ419 (MY:99, Santana)

Samurai/SJ SJ419D (MY:99, Santana)

Samurai/SJ SJ419TD (MY:99, Santana)

Vitara/Sidekick SE419D (MY:96, 5DR Santana)

Vitara/Sidekick SE419TD (MY:97-98,Santana)


Vitara/Sidekick SE416 (MY:97-98, Santana)

Vitara/Sidekick SE416 (MY:96, 3DR Santana)

Vitara/Sidekick SE419D (MY:96, 3DR Santana)

Vitara/Sidekick SE416 (MY:96, 5DR Santana)







GRUPO JPG S.A.
RECAMBIO ORIGINAL
GENUINE PARTS



P/NO: 17887-86CA0

Cant.: 1

TUBO DE LONGITUD 186

