



CONCESIONARIO OFICIAL SANTANA

SANTANA - 64660-66A00 - SOPORTE MOLDURA LAT. L/I

Soporte moldura lateral izquierda

HOLDER, RR LH SPLASH GUARD

SUPPORT, PARE-ÉCLABOUSSURES ARRIÈRE GAUCHE

Vehículo Códigos de modelo Código de modelo

Vitara/Sidekick SE416 SE416-5 TYPE 5

Vitara/Sidekick SV418 SV418 (MY 1997) 97 MODEL SV418

Vitara/Sidekick SE416 SE416-4 TYPE 4

Vitara/Sidekick SV418 SV418 (MY 1996) 96 MODEL SV418

Vitara/Sidekick SE419 SE419TD (MY:97-98,Santana)

Vitara/Sidekick SE416 SE416 (E03,E28,E33,E60:MY 1998) 98 MODEL SE416

Vitara/Sidekick SE416 SE416 (MY:97-98, Santana)


Vitara/Sidekick SE416 SE416 (E03,E28,E33,E60:MY 1997) 97 MODEL SE416

Vitara/Sidekick SE416 SE416 (E03,E28,E33,E60:MY 1996) 96 MODEL SE416

Vitara/Sidekick SE416 SE416 E-III (Santana)

Vitara/Sidekick SV418 SV418 (MY 1998) 98 MODEL SV418

Vitara/Sidekick SE420 SE420 HDI 3DR (Santana) 3DR



SE416 4 E01_178
SIDE BODY PANEL(C)