



CONCESIONARIO OFICIAL SANTANA

SANTANA - 77515-61A00-5PK - JUNTA MOLDURA TECHO

Junta moldura techo

JOINT, ROOF DRIP SIDE MOLDING

JOINT DE MOULURE LATÉRALE D'ÉGOUTTEMENT DE TOIT

GUARNIZIONE MODANATURA LATERALE SCARICO TETTO

DICHTUNG SEITENFORMTEIL FÜR DACHRINNEN

Vehiculo Códigos de modelo Código de modelo

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1991) 91 MODEL

Vitara/Sidekick SE416 SE416 (3DR) TYPE 1

Vitara/Sidekick SE416 SE416 (E24) TYPE 1

Vitara/Sidekick SE416 SE416-2 (E24) TYPE 2

Vitara/Sidekick SE416 SE416-3 (3DR) TYPE 3

Vitara/Sidekick SE416 SE416-2 (3DR) TYPE 2

Vitara/Sidekick SE416 SE416-3 (E24) TYPE 3


Vitara/Sidekick SE416 SE416 (E28:MY 1989) 89 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1991) 91 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1990) 90 MODEL

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1989) 89 MODEL

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1990) 90 MODEL



SE416 3DR E01 252
GARNISH/MOLDING (V)