



CONCESIONARIO OFICIAL SANTANA

SANTANA - 77541-77E01-Z0N - MOLDURA INF.LATERAL DER.

Moldura inferior lateral derecha

GUARD, SIDE SILL SPLASH RH

PROTÈGE-ÉCLABOUSSURE DE SEUIL LATÉRAL DROIT

Vehículo

Vitara/Sidekick SV418 (MY 1997) SV418 97 MODEL

Vitara/Sidekick SV418 (MY 1996) SV418 96 MODEL

Vitara/Sidekick SV420D SV420D

Vitara/Sidekick SV620 SV620

Vitara/Sidekick SV418 (MY 1998) SV418 98 MODEL

Vitara/Sidekick SV620-2 SV620

Vitara/Sidekick SV420D-2 SV420D

Escudo

