



SANTANA - 77575-61A00-5PK - MOLDURA LAT. L/I

Moldura lateral lado izquierda

MOLDING, ROOF DRIP SIDE LH
MOULURE, GOUTTIÈRE DE TOIT GAUCHE

Vehículo Códigos de modelo Código de modelo

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1991) 91 MODEL

Vitara/Sidekick SE420 SE420 HDI 3DR (Santana) 3DR

Vitara/Sidekick SE416 SE416 (E28:MY 1989) 89 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1991) 91 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1990) 90 MODEL

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1989) 89 MODEL

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1990) 90 MODEL

