



CONCESIONARIO OFICIAL SANTANA

SANTANA - 13975-86CB0 - MANGUITO RETORNO ACEITE

Manguito retorno aceite

OIL RETURN HOSE

TUYAU DE RETOUR D'HUILE

TUBO DI RITORNO DELL'OLIO

ÖLRÜCKLAUF SCHLAUCH

Marca Referencia

Suzuki 1397586CB0

Vehículo ??dificación

Vitara/Sidekick SE419D (Santana)

Samurai/SJ SJ419 (MY:99, Santana)

Samurai/SJ SJ419D (MY:99, Santana)

Samurai/SJ SJ419TD (MY:99, Santana)

Vitara/Sidekick SE419TD (MY:97-98, Santana)

Vitara/Sidekick SE416 (MY:97-98, Santana)



