



CONCESIONARIO OFICIAL SANTANA

SANTANA - 76141-81A10-T01 - GUARNICION INF.LAT.DEL.IZQ.

Tapiceria lado izquierdo salpicadero

Vehiculo Código de modelo Modificación Modelo Tipo fuel

Jimny SN413 SN413V-3 SN413V TYPE 3 PETROL

Jimny SN413 SN413V PETROL

Jimny SN413 SN413V-2 (SANTANA) TYPE 2 PETROL

Jimny SN415 SN415QD (SANTANA) DIESEL

Jimny SN415 SN415VD-4 DIESEL SN415VD TYPE 4

Jimny SN413 SN413V-4 SN413V TYPE 4 PETROL

Jimny SN413 SN413Q (SANTANA) TYPE 1

Jimny SN413 SN413Q-2 (SANTANA) TYPE 2

Jimny SN413 SN413V-2 SN413V TYPE 2 PETROL

